

V01	UBICACION
9	Av. Cordoba (7-pb/2-3ºp)
2	Ochava (pb)
8	Libertad (6-pb/2-3ºp)
<div data-bbox="628 465 804 819" data-label="Image"> <p>Technical drawing of a door. The drawing shows a vertical rectangular door with a central panel and a smaller panel above it. The height is labeled as 0.82 and the width is labeled as 0.35.</p> </div> <div data-bbox="600 987 916 1406" data-label="Image"> <p>Photograph of a wooden door with a metal frame. The door is dark brown and has a central panel. The frame is made of dark metal with decorative elements. The door is set in a stone wall.</p> </div>	
DESCRIPCION DE COMPONENTES	
Marco madera (cedro)	
Contramarco moldurado (cedro)	
Hoja: madera	
Contravidrio : madera	
Vidrio:	
Herraje	
Pintura:	
Apertura: abrir	
OBSERVACIONES	
<p><b>Teatro Nacional Cervantes/ Relevamiento de Carpinterías exteriores</b></p>	